



**JABATAN LAUT SEMENANJUNG MALAYSIA
IBU PEJABAT LAUT WILAYAH UTARA
JALAN AKUARIUM
11700 GELUGOR
PULAU PINANG
MALAYSIA.**

Telefon : 04-6578494 / 6579636 / 6574460 Emel : pjlwt@marine.gov.my
Faks : 04-6575521 Laman Web : <http://www.marine.gov.my>



Cert. No : KLR 0403591 E

PEKELILING PELABUHAN NO.02 TAHUN 2009

DARIPADA : PENGARAH LAUT WILAYAH UTARA
KEPADA : MASYARAKAT PERKAPALAN WILAYAH UTARA
TARIKH : 16 JANUARI 2009

TANDARAH SUAR DI PULAU ENGGANG LANGKAWI TIDAK MENYALA

Masyarakat perkapalan adalah dimaklumkan bahawa tandarah suar di Pulau Enggang, Langkawi adalah tidak berfungsi untuk sementara waktu. Butiran tandarah suar adalah seperti berikut :-

Nama : Tandarah Suar Pulau Enggang
Posisi : Lat : 06° 14' 30.00" N
Long : 099° 52' 36.00" E

Sifat lampu : FL.W.8s

Semua kapal yang melalui kawasan tersebut hendaklah belayar dengan berhati-hati.

BEACON AT PULAU ENGGANG LANGKAWI TEMPORARILY UNLIT

The Shipping Community is hereby informed that beacon at Pulau Enggang Langkawi is temporarily unlit. Particulars of the beacon are as follows :-

Name : Pulau Enggang Beacon
Position : Lat : 06° 14' 30.00" N
Long : 099° 52' 36.00" E

Light Characteristic : FL.W.8s

Mariners are advised to exercise caution while navigating in this vicinity.

(ROSLEE BIN MAT YUSOF)
Pengarah Laut Wilayah Utara
Pulau Pinang.

