



JABATAN LAUT WILAYAH TENGAH
(SELANGOR, NEGERI SEMBILAN & MELAKA)
PETI SURAT 268, JALAN FORESHORE
42000 PELABUHAN KLANG
SELANGOR, MALAYSIA

Telefon: 03-3169 5100
 Faks: 03-3165 3540

Emel : pjlwt@marine.gov.my
 Laman Web : <http://www.marine.gov.my>
 Kawat : MARINE PELABUHAN KLANG



MS ISO 9001
 Cert. No : KLR 0403591 B
 Cert. No : KLR 0403591 N
 Cert. No : KLR 0403591 M

PEKELILING PELABUHAN NO. 01/2009
PORT CIRCULAR NO. 01/2009

DARIPADA : PENGARAH LAUT WILAYAH TENGAH
 FROM : DIRECTOR OF MARINE CENTRAL REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN
 PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA
 TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS &
 AGENTS AND THE GENERAL SHIPPING COMMUNITY

TARIKH / DATED : 5hb MEI 2009 / 5th MAY 2009

KERJA-KERJA Pengerukan Kecemasan
DI LABUHAN UNTUK PELABUHAN UTARA
DAN PELABUHAN BARAT, PELABUHAN
KELANG, MALAYSIA

Adalah dimaklumkan bahawa kerja-kerja pengerukan di dermaga Pelabuhan Utara dan Pelabuhan Barat akan dijalankan oleh Syarikat Integrated Marine Works dan butiran kerja-kerja pengerukan adalah seperti berikut ;

Tarikh : 6hb Mei 2009 hingga 6hb Mac 2010

Kawasan Pengerukan :

a) Pelabuhan Utara (Dermaga 17 - 20)

	Latitude	Longitude
A	03° 02' 00.65" N	101° 21' 25.80" E
B	03° 02' 00.56" N	101° 21' 24.18" E
C	03° 01' 57.05" N	101° 21' 22.65" E
D	03° 02' 28.26" N	101° 21' 22.65" E

b) Pelabuhan Barat (Dermaga B1-B-B16)

	Latitude	Longitude
A	02° 57' 31" N	101° 18' 30" E
B	02° 57' 36" N	101° 18' 27" E
C	02° 56' 40" N	101° 18' 00" E
D	02° 56' 42" N	101° 17' 58" E
E	03° 18' 19" N	100° 54' 34" E
F	02° 55' 34" N	101° 17' 19" E

EMERGENCY DREDGING WORKS AT WHARF
FOR NORTH PORT AND WEST PORT,
KELANG PORT, MALAYSIA

This is to notify that the dredging works at North Port and West Port wharf will be carried out by Integrated Marine Works and the details of the dredging works are as follows ;

Dates : 6th May 2009 to 6th March 2010

Dredging Area :

a) North Port (Wharf 17 - 20)

	Latitude	Longitude
A	03° 02' 00.65" N	101° 21' 25.80" E
B	03° 02' 00.56" N	101° 21' 24.18" E
C	03° 01' 57.05" N	101° 21' 22.65" E
D	03° 02' 28.26" N	101° 21' 22.65" E

b) West Port (Berth B1-B-B16)

	Latitude	Longitude
A	02° 57' 31" N	101° 18' 30" E
B	02° 57' 36" N	101° 18' 27" E
C	02° 56' 40" N	101° 18' 00" E
D	02° 56' 42" N	101° 17' 58" E
E	03° 18' 19" N	100° 54' 34" E
F	02° 55' 34" N	101° 17' 19" E

Kawasan Pelupusan :

	Latitude	Longitude
A	02° 56' 33" N	101° 07' 16" E
B	02° 54' 00" N	101° 10' 05" E
C	02° 54' 57" N	101° 05' 50" E
D	02° 54' 29" N	101° 07' 58" E

Vesel yang terlibat :

Nama Vesel	Jenis Vesel
Inai Melawis	Grab Dredger
Inai Teratai 113	Bot Tunda
Inai Teratai 33	Bot Tunda
Inai Teratai 88	Bot Tunda
Inai Lily 11	Bot Sauh
Inai Rose 1202	Split Hopper
Inai Rose 33	Split Hopper

Carta terlibat ;

MAL 5307, 5300

Semua vesel-vesel dan pelaut-pelaut adalah dinasihatkan untuk menjauhi dan berhati-hati apabila berhampiran dengan kawasan berkerja.

Sekian, terima kasih.

"BERKHIDMAT UNTUK NEGARA"

Saya yang menurut perintah,

(HAZMAN BIN HUSSEIN)

Pengarah Laut / Director of Marine
Wilayah Tengah / Central Region

Dumping Ground :

	Latitude	Longitude
A	02° 56' 33" N	101° 07' 16" E
B	02° 54' 00" N	101° 10' 05" E
C	02° 54' 57" N	101° 05' 50" E
D	02° 54' 29" N	101° 07' 58" E

Vessel Involved :

Name of Vessel	Type of Vessel
Inai Melawis	Grab Dredger
Inai Teratai 113	Tug Boat
Inai Teratai 33	Tug Boat
Inai Teratai 88	Tug Boat
Inai Lily 11	Anchor Boat
Inai Rose 1202	Split Hopper
Inai Rose 33	Split Hopper

Chart effected ;

MAL 5307, 5300

All vessel and mariners in the vicinity are advised to navigate with caution and keep clear of the working area.

Thank you.

