



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH UTARA
JALAN AKUARIUM
11700 GELUGOR
PULAU PINANG
JALAN AKUARIUM



Tel : 04-6579636
Faks : 04-6575521
Laman Web : www.marine.gov.my

PEKELILING PELABUHAN BIL. 19/2021
PORT CIRCULAR NO.19/2021

DARIPADA : PENGARAH LAUT WILAYAH UTARA
FROM : *DIRECTOR OF MARINE NORTHERN REGION*

KEPADA : MASYARAKAT PERKAPALAN
TO : *GENERAL SHIPPING COMMUNITY*

TARIKH : 29 Julai 2021
DATE : *29 July 2021*

CARTA BERKAITAN : MAL 5536
RELEVANT CHART

PEMAKLUMAN KERJA-KERJA MEMBAIKPULIH KABEL ELEKTRIK DASAR LAUT DARI QUEENSBAY KE PULAU JEREJAK PULAU PINANG

Masyarakat perkapalan adalah dimaklumkan bahawa terdapat kerja-kerja membaikpulih kabel elektrik dasar laut dari Queensbay ke Pulau Jerejak Pulau Pinang seperti berikut : -

Kedudukan :

- A. Lat 5° 20.24300'N ; Long :100 ° 18' 60200'E
- B. Lat 5° 20.23300'N ; Long :100 ° 18' 63100'E
- C. Lat 5° 20.23000'N ; Long :100 ° 18' 63700'E
- D. Lat 5° 20.22300'N ; Long :100 ° 18' 64600'E
- E. Lat 5° 20.21900'N ; Long :100 ° 18' 65400'E
- F. Lat 5° 20.21500'N ; Long :100 ° 18' 66000'E
- G. Lat 5° 20.21400'N ; Long :100 ° 18' 66300'E
- H. Lat 5° 20.21200'N ; Long :100 ° 18' 66500'E
- I. Lat 5° 20.21000'N ; Long :100 ° 18' 67000'E
- J. Lat 5° 20.17900'N ; Long :100 ° 18' 74300'E
- K. Lat 5° 20.12500'N ; Long :100 ° 18' 85600'E
- L. Lat 5° 19.95308'N ; Long :100 ° 19' 01853'E
- M. Lat 5° 19.90200'N ; Long :100 ° 19' 02700'E
- N. Lat 5° 19.89500'N ; Long :100 ° 19' 02900'E
- O. Lat 5° 19.88900'N ; Long :100 ° 19' 02900'E
- P. Lat 5° 19.87300'N ; Long :100 ° 19' 01800'E

Tarikh kerja bermula dari 01 Ogos – 20 September 2021

Perhatian :

Semua kapal diminta untuk berhati-hati apabila menghampiri kawasan tersebut

“Safer Ships, Secure Ports, Cleaner Seas”



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602

**NOTICE OF MAINTENANCE WORKS OF SUBMARINE ELECTRIC CABLE FROM
QUEENSBAY TO PULAU JEREJAK PULAU PINANG**

The Shipping Communities are hereby informed that, there are maintenance works of submarine electric cable from Queensbay to Pulau Jerejak Pulau Pinang as follows: -

Location :

- A. Lat 5° 20.24300'N ; Long :100 ° 18' 60200'E
- B. Lat 5° 20.23300'N ; Long :100 ° 18' 63100'E
- C. Lat 5° 20.23000'N ; Long :100 ° 18' 63700'E
- D. Lat 5° 20.22300'N ; Long :100 ° 18' 64600'E
- E. Lat 5° 20.21900'N ; Long :100 ° 18' 65400'E
- F. Lat 5° 20.21500'N ; Long :100 ° 18' 66000'E
- G. Lat 5° 20.21400'N ; Long :100 ° 18' 66300'E
- H. Lat 5° 20.21200'N ; Long :100 ° 18' 66500'E
- I. Lat 5° 20.21000'N ; Long :100 ° 18' 67000'E
- J. Lat 5° 20.17900'N ; Long :100 ° 18' 74300'E
- K. Lat 5° 20.12500'N ; Long :100 ° 18' 85600'E
- L. Lat 5° 19.95308'N ; Long :100 ° 19' 01853'E
- M. Lat 5° 19.90200'N ; Long :100 ° 19' 02700'E
- N. Lat 5° 19.89500'N ; Long :100 ° 19' 02900'E
- O. Lat 5° 19.88900'N ; Long :100 ° 19' 02900'E
- P. Lat 5° 19.87300'N ; Long :100 ° 19' 01800'E

Working date start from 01 August – 20 September 2021

Caution:

All vessels are kindly advised to keep clear and navigate with caution when approaching the area

(NUR IZZATI BT NURHALIMI)
b.p Pengarah Laut Wilaya Utara
For Director Of Marine
Northern Region

“Safer Ships, Secure Ports, Cleaner Seas”



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602