



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH UTARA
JALAN AKUARIUM
11700 GELUGOR
PULAU PINANG

Tel : 604-6579636
Faks : 604-6575521
Laman Web : www.marine.gov.my

PEKELILING PELABUHAN NO.28/2017
PORT CIRCULAR NO. 28/2017

DARIPADA : PENGARAH LAUT WILAYAH UTARA
FROM : *DIRECTOR OF MARINE NORTHERN REGION*

KEPADA : MASYARAKAT PERKAPALAN
TO : *GENERAL SHIPPING COMMUNITY*

TARIKH : 11 Julai 2017
DATE : *11 Julai 2017*

CARTA BERKAITAN : MAL 5529
RELEVANT CHART

PEMASANGAN BOYA ISOLATED DANGER MARK

Masyarakat perkapalan adalah dimaklumkan pemasangan boya isolated danger mark di tempat Tandarh Suar Aston di laporkan hilang di kedudukan ; *Lat : 05°24'35"N ; Long : 100°20'68"E* di Pelabuhan Pulau Pinang.

Semua vesel diminta untuk menjauhi dan berhati-hati apabila berhampiran dengan kawasan tandarh suar tenggelam.

INSTALLATION ISOLATED DANGER MARK BUOYS

Mariners are informed that the Installation of the Isolated Danger Mark buoys in the Aston Observatory is reportedly missing in position, Lat : 05°24'35"N ; Long : 100°20'68"E at Port of Penang.

Vessel are advised to navigate with extreme when navigating in vicinity and give wide berth as possible from beacon wreckage

(KAPT ABDUL SAMAD BIN SHAIK OSMAN)
Pengarah Laut Wilayah Utara
Director Of Marine Northern Region

"Ke Arah Negara Kelautan Elektronik"
"Towards e-Maritime Nation"



Cert. No : MAS 101138 (B)