



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH UTARA
JALAN AKUARIUM
11700 GELUGOR
PULAU PINANG
JALAN AKUARIUM



Tel : 04-6579636
Faks : 04-6575521
Laman Web : www.marine.gov.my

PEKELILING PELABUHAN BIL. 25/2021
PORT CIRCULAR NO.25/2021

DARIPADA : PENGARAH LAUT WILAYAH UTARA
FROM : DIRECTOR OF MARINE NORTHERN REGION

KEPADA : MASYARAKAT PERKAPALAN
TO : GENERAL SHIPPING COMMUNITY

TARIKH : 13 Oktober 2021
DATE : 13 October 2021

CARTA BERKAITAN : MAL 5536
RELEVANT CHART

**PEMAKLUMAN KERJA-KERJA MEMBAIKPULIH KABEL ELEKTRIK DASAR LAUT DARI
QUEENSBAY KE PULAU JEREJAK PULAU PINANG**

Masyarakat perkapalan adalah dimaklumkan bahawa terdapat kerja-kerja membaikpulih kabel elektrik dasar laut dari Queensbay ke Pulau Jerejak Pulau Pinang seperti berikut : -

Kedudukan :

- A. Lat 5° 20.24300'N ; Long :100 ° 18' 60200'E
- B. Lat 5° 20.23300'N ; Long :100 ° 18' 63100'E
- C. Lat 5° 20.23000'N ; Long :100 ° 18' 63700'E
- D. Lat 5° 20.22300'N ; Long :100 ° 18' 64600'E
- E. Lat 5° 20.21900'N ; Long :100 ° 18' 65400'E
- F. Lat 5° 20.21500'N ; Long :100 ° 18' 66000'E
- G. Lat 5° 20.21400'N ; Long :100 ° 18' 66300'E
- H. Lat 5° 20.21200'N ; Long :100 ° 18' 66500'E
- I. Lat 5° 20.21000'N ; Long :100 ° 18' 67000'E
- J. Lat 5° 20.17900'N ; Long :100 ° 18' 74300'E
- K. Lat 5° 20.12500'N ; Long :100 ° 18' 85600'E
- L. Lat 5° 19.95308'N ; Long :100 ° 19' 01853'E
- M. Lat 5° 19.90200'N ; Long :100 ° 19' 02700'E
- N. Lat 5° 19.89500'N ; Long :100 ° 19' 02900'E
- O. Lat 5° 19.88900'N ; Long :100 ° 19' 02900'E
- P. Lat 5° 19.87300'N ; Long :100 ° 19' 01800'E

Tarikh kerja bermula 15 Oktober - 30 November 2021

Perhatian :

Semua kapal diminta untuk berhati-hati apabila menghampiri kawasan tersebut

“Safer Ships, Secure Ports, Cleaner Seas”



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602

**NOTICE OF MAINTENANCE WORKS OF SUBMARINE ELECTRIC CABLE FROM
QUEENSBAY TO PULAU JEREJAK PULAU PINANG**

The Shipping Communities are hereby informed that, there are maintenance works of submarine electric cable from Queensbay to Pulau Jerejak Pulau Pinang as follows: -

Location :

- A. Lat 5° 20.24300'N ; Long :100 ° 18' 60200'E
- B. Lat 5° 20.23300'N ; Long :100 ° 18' 63100'E
- C. Lat 5° 20.23000'N ; Long :100 ° 18' 63700'E
- D. Lat 5° 20.22300'N ; Long :100 ° 18' 64600'E
- E. Lat 5° 20.21900'N ; Long :100 ° 18' 65400'E
- F. Lat 5° 20.21500'N ; Long :100 ° 18' 66000'E
- G. Lat 5° 20.21400'N ; Long :100 ° 18' 66300'E
- H. Lat 5° 20.21200'N ; Long :100 ° 18' 66500'E
- I. Lat 5° 20.21000'N ; Long :100 ° 18' 67000'E
- J. Lat 5° 20.17900'N ; Long :100 ° 18' 74300'E
- K. Lat 5° 20.12500'N ; Long :100 ° 18' 85600'E
- L. Lat 5° 19.95308'N ; Long :100 ° 19' 01853'E
- M. Lat 5° 19.90200'N ; Long :100 ° 19' 02700'E
- N. Lat 5° 19.89500'N ; Long :100 ° 19' 02900'E
- O. Lat 5° 19.88900'N ; Long :100 ° 19' 02900'E
- P. Lat 5° 19.87300'N ; Long :100 ° 19' 01800'E

Working date start from 15 October – 30 November 2021

Caution:

All vessels are kindly advised to keep clear and navigate with caution when approaching the area

(NUR IZZATI BT NURHALIMI)
b.p Pengarah Laut Wilaya Utara
For Director Of Marine
Northern Region

“Safer Ships, Secure Ports, Cleaner Seas”



CERTIFIED TO ISO 9001:2015

CERT. NO.: QMS 03602