



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH SELATAN
81560 GELANG PATAH
JOHOR DARUL TA'ZIM

Tel : 07-5072313
Faks : 07-5073679
Laman Web : www.marine.gov.my
Emel : plwst@marine.gov.my



PEKELILING PELABUHAN NO. 83/2018
PORT CIRCULAR NO. 83/2018

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
FROM : DIRECTOR OF MARINE SOUTHERN REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK KAPAL &
AGEN PERKAPALAN DAN MASYARAKAT PERKAPALAN
AMNYA
TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS
AND THE GENERAL SHIPPING COMMUNITY

TARIKH/DATED : 26 SEPTEMBER 2018 / 26 SEPTEMBER 2018

KAWASAN BEKERJA BAGI KONTRAK
"ENGINEERING, PROCUMENT, CONSTRUCTION
AND COMMISSIONING" (EPCC) UNTUK JETI
BARU BAGI PEMUNGGAHAN ARANG BATU
DAN BAHAN-BAHAN PUKAL YANG
BERKAITAN SISTEM 1 X 1000MW LOJI
KUASA ARANG BATU DI TANJUNG BIN,
JOHOR OLEH TANJUNG BIN ENERGY SDN
BHD

WORKING AREA FOR ENGINEERING,
PROCUMENT ,CONSTRUCTION AND
COMMISSIONING (EPCC) CONTRACT FOR
NEW COAL LOADING JETTY AND
ASSOCIATED BULK MATERIAL SYSTEM 1
X 1000MW COAL FIRED POWER PLANT
AT TANJUNG BIN, JOHOR BY TANJUNG
BIN ENERGY SDN BHD

- TAMBAHAN VESEL BEKERJA

Dengan merujuk kepada *Pekeliling Pelabuhan No. 17/2017* bertarikh 03 Ogos 2017, berikut adalah senarai vesel bekerja tambahan:

Tempoh kerja: Sehingga 28 Febuari 2019

Vesel-Vesel Bekerja Tambahan:

Nama Vesel	Jenis Vesel	No. IMO
NAUTILUS 1	BOT TUNDA	336710
NAUTILUS 2	BOT TUNDA	336731
MANJUNG	BARJ	332313

- ADDITIONAL WORKING VESSELS

With reference to *Port Circular No. 17/2017* dated 03 August 2017, listed below are additional working vessels as follows:

Duration of Work: Until 28 February 2019

Additional Working Vessels:

Name of vessel	Type of Vessel	IMO. No
NAUTILUS 1	BOT TUNDA	336710
NAUTILUS 2	BOT TUNDA	336731
MANJUNG	BARJ	332313

PERHATIAN

Semua vesel-vesel yang melayari Sungai Pulai hendaklah belayar dengan berhati-hati apabila menghampiri kawasan kerja tersebut.

Carta-carta terlibat: MAL 5123; BA 4038

Terima kasih.

Saya yang menjalankan amanah,


(HJ DICKSON BIN DOLLAH)
Pengarah Laut / Director of Marine
Jabatan Laut Malaysia
Marine Department Malaysia
Wilayah Selatan
Southern Region

CAUTION

Vessels navigating in Sungai Pulai are required to navigate with caution when approaching the working area.

Charts affected: MAL 5123; BA 4038

Thank you.