



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH SELATAN,
81560 GELANG PATAH,
JOHOR DARUL TA'ZIM



Tel : 07-5072313
Faks : 07-5073679
Laman Web : www.marine.gov.my
Emel : pjlwst@marine.gov.my

PEKELILING PELABUHAN NO. 58/2018
PORT CIRCULAR NO. 58/2018

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
FROM : DIRECTOR OF MARINE SOUTHERN REGION

KEPADA: SEMUA NAKHODA KAPAL, PELAUT, PEMILIK KAPAL & AGEN
PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA.
TO: ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS AND
THE GENERAL SHIPPING COMMUNITY.

TARIKH/DATED : 05 OGOS 2018 / 05 AUGUST 2018

PENEMPATAN PELAMPUNG
NAVIGASI 'SPECIAL MARK' DI SG
PULAI PELABUHAN TANJUNG
PELEPAS, JOHOR.

NEWLY ESTABLISHED NAVIGATION
BUOYS 'SPECIAL MARK' AT SG PULAI
PELABUHAN TANJUNG PELEPAS,
JOHOR.

Ini adalah untuk memaklumkan bahawa pelampung pandu yang baru telah ditempatkan di Pelabuhan Tanjung Pelepas, melalui kawasan pembinaan jambatan Sg. Pulai, di dalam had pelabuhan Tanjung Pelepas seperti berikut :-

Butiran Pelampung Navigasi :-

Nama	Kedudukan (Latitud dan Longitud)	Sifat Lampu
SG.P.NO.1 Special Mark	01° 22.825' Utara 103° 32.158' Timur	Fl.(2)Y.6s
SG.P.NO.2 Special Mark	01° 22.718' Utara 103° 32.174' Timur	Fl.(2)Y.6s
SG.P.NO.3 Special Mark	01° 22.833' Utara 103° 32.211' Timur	Fl.Y.5s
SG.P.NO.4 Special Mark	01° 22.726' Utara 103° 32.227' Timur	Fl.Y.5s

This is to notify that new navigation buoys have been established at the construction site of Sg. Pulai bridge within the port limit of Tanjung Pelepas as follows: -

Particulars of Navigation Buoys :-

Name	Location (Latitude and Longitude)	Light Characteristics
SG.P.NO.1 Special Mark	01° 22.825' Nort 103° 32.158' East	Fl.(2)Y.6s
SG.P.NO.2 Special Mark	01° 22.718' Nort 103° 32.174' East	Fl.(2)Y.6s
SG.P.NO.3 Special Mark	01° 22.833' Nort 103° 32.211' East	Fl.Y.5s
SG.P.NO.4 Special Mark	01° 22.726' Nort 103° 32.227' East	Fl.Y.5s

"Ke Arah Negara Kelautan Elektronik"
"Towards e-Maritime Nation"



Cert. No : KLR 0403591 B1

PEKELILING PELABUHAN NO. 58/2018

PERHATIAN:

Semua pelaut-pelaut dinasihatkan mengambil maklum akan penempatan baru pelampung pandu tersebut.

Carta Terlibat : MAL 5123

Terima kasih.

PORT CIRCULAR NO. 58/2018

CAUTION:

All mariners are advised to take note of the newly established navigational buoys.

Charts Affected : MAL 5123

Thank you

Saya yang menurut perintah,



(HJ.DICKSON BIN DOLLAH)
Pengarah Laut / *Director of Marine*
Jabatan Laut Malaysia
Marine Department Malaysia
Wilayah Selatan
Southern Region