



**JABATAN LAUT SEMENANJUNG MALAYSIA,
IBU PEJABAT LAUT WILAYAH TIMUR,
JALAN HILIRAN,
20300 KUALA TERENGGANU.
TERENGGANU DARUL IMAN.**

Telefon : 09 - 622 1471/ 9473/9478 Emel : plwtm@marine.gov.my
Faks : 09 - 623 3676 Laman Web : <http://www.marine.gov.my>



MS ISO 9001
Approval Cert. No : 403591 A
Approval Cert. No : 403591 C
Approval Cert. No : 403591 D

**PEKELILING PELABUHAN BIL
13/2005**

DARIPADA PENGARAH LAUT WILAYAH
TIMUR
KEPADA SEMUA NAKHODA KAPAL,
PELAUT, PEMILIK & AGEN
PERKAPALAN
DAN MASYARAKAT
PERKAPALAN AMNYA

TARIKH 31 Mei 2005

**BOYA NORTH CARDINAL MARK
TELAH HANYUT**

KETERANGAN:

Adalah dimaklumkan bahawa Boya North Cardinal Mark di kedudukan Lat: 04° 14' 00" U Long: 103° 27' 17" T di Kuala Kemaman telah hanyut dan di dikeluarkan dari kedudukan.

PERINGATAN

Masyarakat perkapalan yang belayar berhampiran dengannya hendaklah belayar dengan berhati-hati.

(ROSSID BIN MUSA)
Pengarah Laut Wilayah Timur,
Kuala Terengganu

**PORT CIRCULAR NO
13/2005**

FROM DIRECTOR OF MARINE EASTERN
REGION
TO ALL SHIP MASTERS, MARINERS,
SHIP OWNSERS & AGENTS AND
THE GENERAL SHIPPING
COMUNITY

DATE 31 Mei 2005

**NORTH CARDINAL MARK HAD
DRIFTED**

DETAILS:

This is to notify that the North Cardinal Mark Buoy at position Lat: 04° 14' 00" N Long: 103° 27' 17" E at Kuala Kemaman was drifted and had been removed from its position.

DETAILS

Mariners are advised to navigate with caution when entering the area.

**Director,
Marine Department Eastern Region,
Kuala Terengganu**