



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH UTARA
JALAN AKUARIUM
11700 GELUGOR
PULAU PINANG

Telefon : 604-6579636
Faksimili : 604-6575521
Laman Web : www.marine.gov.my



PEKELILING PELABUHAN BIL.02/2021
PORT CIRCULAR NO.02/2021

DARIPADA : PENGARAH LAUT WILAYAH UTARA
FROM : DIRECTOR OF MARINE NORTHERN REGION

KEPADA : MASYARAKAT PERKAPALAN
TO : GENERAL SHIPPING COMMUNITY

TARIKH : 15 JANUARI 2021
DATE : 15 JANUARY 2021

CARTA BERKAITAN: MAL 554
RELEVANT CHART : MAL 554

LAMPU PELAMPUNG PANDU LEKIR NO.1R TIDAK MENYALA

Masyarakat Perkapalan adalah dimaklumkan bahawa lampu pelampung pandu tidak menyala di lokasi dan butiran seperti berikut:-

1. Pelampung Pandu Lekir No.1R - 04°08.70'N , 100°34.52'E

Semua pelaut dan vessel dinasihatkan agar berhati-hati ketika belayar di kawasan tersebut.

LIGHT OF BUOY LEKIR NO.1R IS UNLIT

The shipping communities are informed that the bouy is unlit on the following location and details:

1. Buoy Lekir No. 1R - 04°08.70'N , 100°34.52'E

All mariner and vessel are advised to be cautious while operating at concerned vicinity.

15/1/2021

(MOHD HAFIZ BIN ABDUL MAJID)
Pengarah Laut Wilayah Utara
Director of Marine Northern Region