



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH UTARA
JALAN AKUARIUM
11700 GELUGOR
PULAU PINANG



Tel : 604-6579636
Faks : 604-6575521
Laman Web : www.marine.gov.my

PEKELILING PELABUHAN BIL. 20/2020
PORT CIRCULAR NO. 20/2020

DARIPADA : PENGARAH LAUT WILAYAH UTARA
FROM : *DIRECTOR OF MARINE NORTHERN REGION*

KEPADA : MASYARAKAT PERKAPALAN
TO : *GENERAL SHIPPING COMMUNITY*

TARIKH : 18 Ogos 2020
DATE : *18th August 2020*

CARTA BERKAITAN : MAL 554
RELEVANT CHART

LAMPU TANDARAH SUAR PULAU KATAK TIDAK MENYALA

Masyarakat Perkapalan adalah dimaklumkan bahawa lampu tandarah suar tidak menyala di lokasi dan butiran seperti berikut -

1. Bikon Pulau Katak – 4° 9.340' N 100° 37.130' E

Semua pelaut dan vesel dinasihatkan agar berhati-hati ketika belayar di kawasan tersebut.

LIGHT OF PULAU KATAK BEACON IS UNLIT

The Shipping Community is informed that the beacon lights are not on at the following locations and details -

1. Pulau Katak Beacon - 4° 9.340 'N 100° 37.130' E

All mariner and vessel are advised to be cautious while operating at the concerned vicinity.

(MOHD HAFIZ BIN ABDUL MAJID)
Pengarah Laut Wilayah Utara