



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH SELATAN,
81560 GELANG PATAH,
JOHOR DARUL TA'ZIM



Tel : 07-5072313
Faks : 07-5073679
Laman Web : www.marine.gov.my
Emel : piwst@marine.gov.my

PEKELILING PELABUHAN NO. 34/2019
PORT CIRCULAR NO. 34/2019

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
FROM : DIRECTOR OF MARINE SOUTHERN REGION

KEPADA: SEMUA NAKHODA KAPAL, PELAUT, PEMILIK KAPAL &
AGEN PERKAPALAN DAN MASYARAKAT PERKAPALAN
AMNYA.

TO: ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS
AND THE GENERAL SHIPPING COMMUNITY.

TARIKH/DATED : 17 OKTOBER 2019 / 17 OCTOBER 2019

**AKTIVITI PENYIASATAN TANAH DALAM
HAD PELABUHAN JOHOR BAHRU, JOHOR.**

Ini adalah untuk memaklumkan bahawa aktiviti penyiasatan tanah akan dilaksanakan didalam Had Pelabuhan Johor Bahru dan butir-butirnya adalah seperti berikut:

Tarikh: 17 Oktober 2019 – 17 November 2019

Waktu-waktu bekerja: Siang hari sahaja

**SOIL INVESTIGATION ACTIVITIES WITHIN
JOHOR BAHRU PORT LIMITS, JOHOR.**

This to notify that soil investigation activities will be conducted within Johor Bahru Port Limits and the details are as follows:

Dates: 17 October 2019 – 29 November 2019

Working hours: Daylight only

KAWASAN BEKERJA:

No.	Latitud Utara	Longitud Timur
1	01° 16.02'	103° 35.26'
2	01° 15.40'	103° 34.04'
3	01° 13.47'	103° 33.69'
4	01° 13.26'	103° 34.49'
5	01° 15.15'	103° 34.80'
6	01° 15.75'	103° 36.00'

WORKING AREA:

No.	Latitude North	Longitude East
1	01° 16.02'	103° 35.26'
2	01° 15.40'	103° 34.04'
3	01° 13.47'	103° 33.69'
4	01° 13.26'	103° 34.49'
5	01° 15.15'	103° 34.80'
6	01° 15.75'	103° 36.00'

PEKELILING PELABUHAN NO. 34/2019

PORT CIRCULAR NO. 34/2019

VESEL BEKERJA:

NAMA VESEL	NO IMO	P.O.R
SAPURA ACHIEVER	9238026	PORT KELANG

WORKING VESSEL:

NAME OF VESSEL	IMO NO	P.O.R
SAPURA ACHIEVER	9238026	PORT KELANG

PERHATIAN

Semua pelaut dan vesel-vesel hendaklah berlayar dengan berhati-hati apabila menghampiri kawasan bekerja tersebut dan menjauhi vesel bekerja berkenaan.

CAUTION

All mariners and vessels are to proceed with caution when approaching the working area and to keep clear of the working vessel.


Carta Terlibat : MAL 5123, BA 4038

Charts affected : MAL 5123, BA 4038

Terima kasih.

Thank you

Saya yang menjalankan amanah,



(HAJI DICKSON DOLLAH)

Pengarah Laut / for Director of Marine
Jabatan Laut Malaysia
Marine Department Malaysia
Wilayah Selatan
Southern Region