



**PEKELILING PELABUHAN
PORT CIRCULAR**

NO. 4/2010



JABATAN LAUT SEMENANJUNG MALAYSIA
Pejabat Laut Wilayah Persekutuan Labuan
Peti Surat 81005, 87020 W.P. Labuan

MS ISO 9001
Cert. No KLR 0403591

Telephone : 087-413511 Email : pjlwplbn@marine.gov.my
Fax : 087-413515 Web Page : <http://www.marine.gov.my>

**PERTUKARAN SIFAT LAMPU TANDARAH SUAR DI W.P LABUAN
LIGHTBEACONS CHARACTERISTIC CHANGES AT W.P LABUAN**

Daripada :	Pegawai Pelabuhan	From :	Port Officer
Kepada :	Masyarakat Perkapalan	To :	Shipping Community
Tarikh :	25hb Mac 2010	Date :	25 th March 2010
Carta Berkaitan :	BA 2111, MAL 872, MAL 752	Relevant Chart :	BA 2111, MAL 872, MAL 752

Masyarakat perkapalan dimaklumkan bahawa julat lampu tandarah suar seperti dibawah telah ditukarkan kepada berikut.

Shipping community are informed that the Lightbeacons as the following had been changed.

Nama : Tanjung Kubong
(Bethune Head)
Lokasi : Lat 05° 23.60' N
Long 115° 14.90' E
Sifat Lampu Asal : FI (2)W 15s 20M
Sifat Lampu Baru : FI (2)W 15s 10M

Name : Tanjung Kubong
(Bethune Head)
Location : Lat 05° 23.60' N
Long 115° 14.90' E
Previous Light Characteristic : FI (2)W 15s 20M
Current Light Characteristic : FI (2)W 15s 10M

Nama : Pulau Papan
Lokasi : Lat 05° 15.24' N
Long 115° 15.95' E
Sifat Lampu Asal : FI W 7s 15M
Sifat Lampu Baru : FI W 7s 10M

Name : Pulau Papan
Location : Lat 05° 15.24' N
Long 115° 15.95' E
Previous Light Characteristic : FI W 7s 15M
Current Light Characteristic : FI W 7s 10M

(RUSLAN BIN HUSIN)
For Director Of Marine
Marine Department Labuan Federal Territory.