



JABATAN LAUT MALAYSIA
PEJABAT LAUT PORT DICKSON
JALAN RAJA AMAN SHAH
71000 PORT DICKSON
NEGERI SEMBILAN DARUL KHUSUS

Telefon: 06-6477993 Emel : ppdks@marine.gov.my
Faks: 06-6477998 Laman Web : <http://www.marine.gov.my>



PEKELILING PELABUHAN PORT DICKSON NO. 15 /2019
PORT DICKSON PORT CIRCULAR NO. 15/2019

DARIPADA : PENGARAH LAUT WILAYAH TENGAH
FROM : DIRECTOR OF MARINE CENTRAL REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN
PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA
TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS &
AGENTS AND THE GENERAL SHIPPING COMMUNITY

TARIKH / DATED : 23 Oktober 2019 / 23rd October 2019

KERJA-KERJA PEMBAIKAN PLEM 32" SINGLE BOUY
MOORING (SBM)

Adalah dimaklumkan Hengyuan Refining Company Berhad akan menjalankan kerja-kerja pembaikan Plem 32" SBM sehingga 02 November 2019.

Lokasi:

Single Bouy Mooring		
Latitud	Longitude	Radius
02° 31.3'N	101° 47.1'E	300 meter

Vasel:

No	Nama	Jenis
1	SSE Francis	Self-Propelled Crane Barge
2	SSE Indiana	Crane barge
3	SSE Elexandria	Work Boat
4	SSE Ignatius	Crane Barge
5	SSE Ronelle	Tug Boat

Perhatian

Semua kapal-kapal dan pelaut-pelaut adalah dinasihatkan untuk menjauhi dan berhati-hati apabila berhampiran dengan kawasan persekitaran tersebut.

Terima kasih.

32 " SINGLE BOUY MOORING (SBM) REPAIR WORK

This is to notify that Hengyuan Refining Company Berhad will carry out the repair work of Plem 32" SBM until November 02, 2019.

Location:

Single Bouy Mooring		
Latitud	Longitude	Radius
02° 31.3'N	101° 47.1'E	300 meter

Vassel involved:

No	Name	type
1	SSE Francis	Self-Propelled Crane Barge
2	SSE Indiana	Crane barge
3	SSE Elexandria	Work Boat
4	SSE Ignatius	Crane Barge
5	SSE Ronelle	Tug Boat

Caution

All vessels and mariners are advised to keep clear of the area and to navigate with caution when in the vicinity.

Thank you.

(MOHAMMAD NAZRI BIN SILIM)
b.p Pengarah Laut Wilayah Tengah
Director of Marine, Central Region