



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH UTARA
JALAN AKUARIUM
11700 GELUGOR
PULAU PINANG
JALAN AKUARIUM



Telefon : 04-6579636
Faks : 04-6575521
Laman Web : www.marine.gov.my

PEKELILING PELABUHAN NO.04/2024
PORT CIRCULAR NO.04/2024

DARIPADA : PENGARAH LAUT WILAYAH UTARA
FROM : DIRECTOR OF MARINE NORTHERN REGION

KEPADA : MASYARAKAT PERKAPALAN WILAYAH UTARA
TO : SHIPPING COMMUNITY NORTHERN REGION

TARIKH : 01 FEBRUARI 2024
DATE : 01st FEBRUARY 2024

CARTA BERKAITAN : MAL 5536, MAL 5425, MAL 5403
RELEVANT CHART

**KAWASAN MELAPOR KEPADA VTMIS BAGI OPERASI KAPAL YANG
TERLIBAT DENGAN PROJEK, BERLABUH TUNGGU, SHIP TO SHIP (STS) DI
PULAU PINANG DAN PERAK**

Masyarakat perkapalan adalah dimaklumkan bahawa berikut adalah kawasan melapor kepada *Vessel Traffic Management and Information System* (VTMIS) bagi kapal-kapal yang beroperasi di Pulau Pinang dan Perak. Setiap kapal yang terlibat dengan aktiviti di atas dikehendaki melapor kepada VTMIS setiap kali keluar dan masuk ke kawasan pada posisi yang telah ditetapkan.

Pulau Pinang		
Kawasan selatan	Rumah Api Pulau Rimau	
	05°14'41" U	
	100°16'30" T	
Kawasan utara	Tandarah Suar Pulau Tikus	
	05°28'35" U	
	100°17'51" T	
Lumut - Teluk Intan, Perak		
Kawasan Lumut	Boya NW3	Tandarah Suar South East Point
	04°16'30" U	04°11'17" U
	100°33'11" T	100°34'53" T
Kawasan Teluk Intan	Tandarah Suar Bagan Datuk	
	03°59'32" U	
	100°45'6" T	

Semua vesel diminta untuk mematuhi seperti arahan yang dikeluarkan.

**REPORTING AREA TO VTMISS FOR SHIP OPERATIONS INVOLVED WITH
PROJECTS, ANCHORED AND WAITING, SHIP TO SHIP (STS) IN PENANG AND
PERAK ISLANDS**

Mariners are informed that the following are the reporting areas to the Vessel Traffic Management and Information System (VTMISS) for vessels operating in Penang and Perak. Each vessel involved in the above activities is required to report to VTMISS every time it leaves and enters the area at the designated position.

Pulau Pinang		
Souther Area	Pulau Rimau Lighthouse	
	05°14'41" N	
	100°16'30" E	
Northern Area	Pulau Tikus Lightbeacon	
	05°28'35" N	
	100°17'51" E	
Lumut - Teluk Intan, Perak		
Lumut Area	NW3 Buoy	South East Point Lightbuoy
	04°16'30" N	04°11'17" N
	100°33'11" E	100°34'53" E
Teluk Intan Area	Bagan Datuk Lightbuoy	
	03°59'32" N	
	100°45'6" E	


All vessels are kindly asked to comply with this instructions.

(MUHAMMAD SHUHAIMI BIN ABDUL RAHMAN)

Pengarah Laut Wilayah Utara
Director Of Marine Northern Region



Pulau Pinang



Lumut - Teluk Intan, Perak