



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH SELATAN,
81560 GELANG PATAH,
JOHOR DARUL TA'ZIM

Tel : 07-5072313
Faks : 07-5073679
Laman Web : www.marine.gov.my
Emel : pjlwst@marine.gov.my



PEKELILING PELABUHAN NO. 40/2019
PORT CIRCULAR NO. 40/2019

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
FROM : DIRECTOR OF MARINE SOUTHERN REGION

KEPADA: SEMUA NAKHODA KAPAL, PELAUT, PEMILIK KAPAL &
AGEN PERKAPALAN DAN MASYARAKAT PERKAPALAN
AMNYA.

TO: ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS
AND THE GENERAL SHIPPING COMMUNITY.

TARIKH/DATED : 3 DISEMBER 2019 / 3 DECEMBER 2019

**AKTIVITI PENGUKURAN HIDROGRAFI
DALAM HAD PELABUHAN TANJUNG
PELEPAS, JOHOR.**

Ini adalah untuk memaklumkan bahawa aktiviti pengukuran akan dilaksanakan di International Petroleum Hub(IPH), Bunker Island dalam Had Pelabuhan Tanjung Pelepas dan butir-butirnya adalah seperti berikut:

Tarikh: 3 Disember 2019 – 25 Disember 2019

Waktu-waktu bekerja: Siang hari sahaja

KAWASAN BEKERJA:

Merangkumi 2 batu nautika dari titik koordinat

No.	Latitud Utara	Longitud Timur
1	01° 18.91'	103° 32.77'

**HYDROGRAFI SURVEY ACTIVITIES WITHIN
TANJUNG PELEPAS PORT LIMITS, JOHOR.**

This to notify that survey activities will be conducted off the International Petroleum Hub(IPH), Bunker Island within Tanjung Pelepas Port Limits and the details are as follows:

² Dates: 3 Disember 2019 – 25 December 2019

Working hours: Daylight only

WORKING AREA:

Radius 2nm from the Coordinate position

No.	Latitude North	Longitude East
1	01° 18.91'	103° 32.77'

PEKELILING PELABUHAN NO. 40/2019

PORT CIRCULAR NO. 40/2019

VESEL BEKERJA:

NAMA VESEL	NO. LESEN	P.O.R
SRI PERKASA 65	JTP 00224P	Tanjung Pelepas

WORKING VESSEL:

NAME OF VESSEL	LICENCE NO.	P.O.R
SRI PERKASA 65	JTP 00224P	Tanjung Pelepas

PERHATIAN:

Semua pelaut dan vesel-vesel hendaklah berlayar dengan berhati-hati apabila menghampiri kawasan bekerja tersebut dan menjauhi vesel bekerja berkenaan.

CAUTION:

All mariners and vessels are to proceed with caution when approaching the working area and to keep clear of the working vessel.


Carta Terlibat : MAL 5123, BA 4038

Charts affected : MAL 5123,,BA 4038

Terima kasih.

Thank you

Saya yang menjalankan amanah,



(HAJI DICKSON DOLLAH)

Pengarah Laut / for Director of Marine
Jabatan Laut Malaysia
Marine Department Malaysia
Wilayah Selatan
Southern Region