



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH SELATAN
81560 GELANG PATAH
JOHOR DARUL TA'ZIM

Tel : 07-5072313
Faks : 07-5073679
Laman Web : www.marine.gov.my
Emel : plwst@marine.gov.my



PEKELILING PELABUHAN NO. 93/2018
PORT CIRCULAR NO. 93/2018

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
FROM : DIRECTOR OF MARINE SOUTHERN REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK KAPAL &
AGEN PERKAPALAN DAN MASYARAKAT PERKAPALAN
AMNYA
TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS
AND THE GENERAL SHIPPING COMMUNITY

TARIKH/DATED : 26 Disember 2018 / 26 December 2018

OPERASI MENCARI DAN MENYELAMAT DI
TELUK RAMUNIA

Ini adalah untuk memaklumkan bahawa operasi mencari dan menyelamat (SAR) sedang dijalankan oleh Agensi Penguatkuasaan Maritim Malaysia, Tentera Laut Diraja Malaysia dan Polis Marin Malaysia untuk mencari seorang krew yang hilang daripada kapal MV AMANDA (IMO: 8695021) akibat daripada terbalik di Teluk Ramunia, Luar Pantai Johor dan butirannya adalah seperti berikut:

Lokasi kapal terbalik, (WGS84)

	Latitud Utara	Latitud Timur
A	01° 25.548'	104° 20.839'

Kapal-kapal terlibat:

- i. KM Niah
- iii. KD Pendekar
- v. PSC 28
- vii. Kilat 11

SEARCH AND RESCUE OPERATION AT
RAMUNIA SHOAL

This is to inform that search and rescue (SAR) operation is being conducted by the Malaysian Maritime Enforcement Agency, Malaysian Royal Navy and Malaysian Marine Police for one(1) missing crew from MV AMANDA (IMO: 8695021) due to capsizing at Ramunia Shoal, Offshore Johor and the details are as follow

Location of capsized ship, (WGS84)

	Latitude North	Longitude East
A	01° 25.548'	104° 20.839'

Vessels involved:

- ii. KM Niah
- iv. KD Pendekar
- vi. PSC 28
- viii. Kilat 11

PEKELILING PELABUHAN NO. 93/2018

PERHATIAN

Semua vesel-vesel yang belayar menghampiri kawasan operasi sepertimana diatas hendaklah membuat awasan rapi dan belayar dengan lebih berhati-hati.

Terima kasih.

Saya yang menjalankan amanah,



(HJ DICKSON BIN DOLLAH)
Pengarah Laut / *Director of Marine*
Jabatan Laut Malaysia
Marine Department Malaysia
Wilayah Selatan
Southern Region

PORT CIRCULAR NO.93/2018

CAUTION

Vessels navigating in the vicinity of the operation area as mentioned above are required to keep a sharp lookout and navigate with extra caution.

Thank you.