



PEKELILING PELABUHAN BIL. 24/2021
PORT CIRCULAR NO. 24/2021

DARIPADA : PENGARAH LAUT WILAYAH TIMUR
FROM : DIRECTOR OF MARINE EASTERN REGION

KEPADA : MASYARAKAT PERKAPALAN
TO : SHIPPING COMMUNITY

TARIKH : 23 Disember 2021
DATED : 23 December 2021

CARTA BERKAITAN : MAL 6416, BA 1374
CHARTS AFFECTED : MAL 6416, BA 1374

**TANDARAH SUAR TANJUNG BERHALA
NO.1 RUNTUH DI PELABUHAN KEMAMAN**

Tandarah Suar Tanjung Berhala No. 1 telah runtuh di Pelabuhan Kemaman, Terengganu. Butiran adalah seperti berikut :-

Nama : Tanjung Berhala No.1
Posisi : Lat 04° 13.732' U
Long 103° 29.265' T
Sifat lampu : Fl.G.5s

Semua vesel adalah dinasihatkan untuk berhati-hati apabila menghampiri kawasan tersebut, belayar dengan kelajuan selamat serta meningkatkan pengawasan

**LIGHT BEACON TANJUNG BERHALA NO.
1 DESTROYED AT KEMAMAN PORT**

Light Beacon Tanjung Berhala No. 1 has been destroyed at Kemaman Port, Terengganu. Particulars are as follows:-.

Name : Tanjung Berhala No.1
Position : Lat 04° 13.732' N
Long 103° 29.265' E
Light : Fl.G.5s
Characteristic

All vessels are advised to navigate with extra cautious, maintain safe speed and proper watchkeeping.

(NOR BAHIRAH BINTI MUHD RAZALI)
b.p Pengarah Laut Wilayah Timur
for Director of Marine Eastern Region