



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH SELATAN,
81560 GELANG PATAH,
JOHOR DARUL TA'ZIM



Tel : 07-5072313
Faks : 07-5073679
Laman Web : www.marine.gov.my
Emel : djlwt@marine.gov.my

PEKELILING PELABUHAN NO. 43/2019
PORT CIRCULAR NO. 43/2019

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
FROM : DIRECTOR OF MARINE SOUTHERN REGION

KEPADA: SEMUA NAKHODA KAPAL, PELAUT, PEMILIK KAPAL &
AGEN PERKAPALAN DAN MASYARAKAT PERKAPALAN
AMNYA.

TO: ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS
AND THE GENERAL SHIPPING COMMUNITY.

TARIKH/DATED : 22 DISEMBER 2019 / 22 DESEMBER 2019

AKTIVITI PENGUKURAN MARIN: DALAM
HAD PELABUHAN TANJUNG PELEPAS ,
JOHOR.

Ini adalah untuk memaklumkan bahawa aktiviti pengukuran akan dilaksanakan di dalam Had Pelabuhan Tanjung Pelepas dan butir-butirnya adalah seperti berikut:

Tarikh: 24 Disember 2019 – 28 Disember 2019

Waktu-waktu bekerja: Siang hari sahaja

MARINE SURVEY ACTIVITIES: WITHIN
TANJUNG PELEPAS PORT LIMITS, JOHOR.

This to notify that survey activities will be conducted at the Tanjung Pelepas Port Limits and the details are as follows:

Dates: 24 Desember 2019 – 20 December 2019

Working hours: Daylight only

KAWASAN BEKERJA:

No.	Latitud Utara	Longitud Timur
1	01° 20.42'	103° 32.82'
2	01° 19.76'	103° 34.08'
3	01° 20.49'	103° 34.04'
4	01° 20.59'	103° 34.85'
5	01° 19.47'	103° 35.63'
6	01° 18.95'	103° 36.33'
7	01° 20.84'	103° 36.98'
8	01° 21.92'	103° 37'98"
9	01° 20.85'	103° 35.51'
10	01° 20.86'	103° 34.99'

WORKING AREA:

No.	Latitude North	Longitude East
1	01° 20.42'	103° 32.82'
2	01° 19.76'	103° 34.08'
3	01° 20.49'	103° 34.04'
4	01° 20.59'	103° 34.85'
5	01° 19.47'	103° 35.63'
6	01° 18.95'	103° 36.33'
7	01° 20.84'	103° 36.98'
8	01° 21.92'	103° 37'98"
9	01° 20.85'	103° 35.51'
10	01° 20.86'	103° 34.99'

PEKELILING PELABUHAN NO. 43/2019

PORT CIRCULAR NO. 43/2019

VESEL BEKERJA:

NAMA VESEL	LESEN NO.
MAHABBAH	JTP 00311P

WORKING VESSEL:

NAME OF VESSEL	LECENCE NO.
MAHABBAH	JTP 00311P

PERHATIAN:

Semua pelaut dan vesel-vesel hendaklah berlayar dengan berhati-hati apabila menghampiri kawasan bekerja tersebut dan menjauhi vesel bekerja berkenaan.

CAUTION:

All mariners and vessels are to proceed with caution when approaching the working area and to keep clear of the working vessel.

Carta Terlibat : MAL 5123, BA 4038

Charts affected : MAL 5123,,BA 4038

Terima kasih.

Thank you

Saya yang menjalankan amanah,

(HAJI DICKSON DOLLAH)
Pengarah Laut / for *Director of Marine*
Jabatan Laut Malaysia
Marine Department Malaysia
Wilayah Selatan
Southern Region