



JABATAN LAUT MALAYSIA
PEJABAT LAUT PORT DICKSON
JALAN RAJA AMAN SHAH
71000 PORT DICKSON
NEGERI SEMBILAN DARUL KHUSUS



Telefon: 06-6477993
Faks: 06-6477998
Emel : ppdks@marine.gov.my
Laman Web : <http://www.marine.gov.my>

PEKELILING PELABUHAN PORT DICKSON NO. 22 /2022
PORT DICKSON PORT CIRCULAR NO. 22 /2022

DARIPADA : PENGARAH LAUT WILAYAH TENGAH
FROM : DIRECTOR OF MARINE CENTRAL REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN
PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA
TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS &
AGENTS AND THE GENERAL SHIPPING COMMUNITY

TARIKH / DATED : 12 September 2022 / 12 September 2022

KERJA-KERJA SELAMAN UNTUK PEMERIKSAAN Q3
TAHUNAN DI SINGLE BOUY MOORING (SBM) HRC

Tempoh:
Dari 16 September 2022 sehingga 22 September 2022

Lokasi:

Single Buoy Mooring (PETRON)		
Latitude	Longitude	Radius
02° 31.3' N	101° 47.1' E	300 meter

Vessel terlibat:

No	Nama	Jenis
1	NPD 00488P	Work Boat

Perhatian

Semua kapal-kapal dan pelaut-pelaut adalah dinasihatkan untuk menjauhi dan berhati-hati apabila berhampiran dengan kawasan persekitaran tersebut.

Terima kasih.

DIVING WORKS FOR ANNUAL Q3 INSPECTION AT
SINGLE BOUY MOORING (SBM) HRC

Duration
From 16 September 2022 until 22 September 2022

Location:

Single Buoy Mooring (PETRON)		
Latitude	Longitude	Radius
02° 31.3' N	101° 47.1' E	300 meter

Vessel involved:

No	Name	Type
1	NPD 00488P	Work Boat

Caution

All vessels and mariners are advised to keep clear of the area and to navigate with caution when in the vicinity.

Thank you.

(MOHD ABDUL HAKIM BIN CHE MOHD NOR)
b.p Pengarah Laut Wilayah Tengah
Director of Marine, Central Region