



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH SELATAN,
81560 GELANG PATAH,
JOHOR DARUL TA'ZIM



Tel : 07-5072313
Faks : 07-5073679
Laman Web : www.marine.gov.my
Emel : plwst@marine.gov.my

PEKELILING PELABUHAN NO. 09/2017
PORT CIRCULAR NO. 09/2017

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
FROM : DIRECTOR OF MARINE SOUTHERN REGION

KEPADA: SEMUA NAKHODA KAPAL, PELAUT, PEMILIK KAPAL & AGEN
PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA.
TO: ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS AND
THE GENERAL SHIPPING COMMUNITY.

TARIKH/DATED : 06 APRIL 2017 / 06 APRIL 2017

**AKTIVITI SURVEI HIDROGRAFI DI HAD
PELABUHAN TANJUNG PELEPAS,
JOHOR.**

Ini adalah untuk memaklumkan bahawa survei hidrografi akan dilaksanakan di sekitar Jambatan Kedua, didalam had pelabuhan Tanjung Pelepas dan butir-butirnya adalah seperti berikut:

Tarikh: 10 April 2017 – 17 April 2017

Waktu bekerja: Ketika cuaca baik sahaja

**HYDROGRAPHIC SURVEYS IN THE
TANJUNG PELEPAS PORT LIMITS,
JOHOR.**

This to notify that hydrographic surveys will be conducted off the Second Link in the Tanjung Pelepas port limits and the details are as follows:

Dates: 10 April 2017 – 17 April 2017

Working hours: In good weather only

KAWASAN BEKERJA WGS84:

No.	<u>Latitud Utara</u> <u>N</u>	<u>Longitud Timur</u> <u>E</u>
1.	01° 21.122'	103° 36.982'
2.	01° 21.815'	103° 37.870'
3.	01° 21.577'	104° 38.193'
4.	01° 20.172'	103° 37.706'

WORKING AREA WGS84:

No.	<u>Latitude North</u> <u>N</u>	<u>Longitude East</u> <u>E</u>
1.	01° 21.122'	103° 36.982'
2.	01° 21.815'	103° 37.870'
3.	01° 21.577'	104° 38.193'
4.	01° 20.172'	103° 37.706'

“Ke Arah Negara Kelautan Elektronik”
“Towards e-Maritime Nation”



PEKELILING PELABUHAN NO. 09/2017

PORT CIRCULAR NO. 09/2017

BOT BEKERJA:

<u>Nama vesel</u>	<u>Jenis Vesel</u>	<u>No: Lesen</u>
OPL MARINE LOGISTIC 04	Bot penumpang	JTP00220P

WORKING BOAT::

<u>Name of vessel</u>	<u>Type of vessel</u>	<u>Licence No:</u>
OPL MARINE LOGISTIC 04	Passenger boat	JTP00220P

PERHATIAN :

Semua vesel-vesel yang bernavigasi di sekitar Jambatan Kedua hendaklah membuat pemerhatian rapi dan menjauhi bot survei tersebut.

CAUTION :

All vessels navigating within the vicinity of Second Link are to keep a sharp lookout and to keep clear of the survey boat.


Carta Terlibat : MAL 5123, BA 4038

Charts affected : MAL 5123, BA 4038

Terima kasih.

Thank you

Saya yang menurut perintah,



(SHAH HABIDIN ARIB BIN JAAFAR)

Pengarah Laut / *Director of Marine*

Jabatan Laut Malaysia

Marine Department Malaysia

Wilayah Selatan

Southern Region

"Ke Arah Negara Kelautan Elektronik"
"Towards e-Maritime Nation"



Cert. No : KLR 0403591 B1