



JABATAN LAUT MALAYSIA
PEJABAT LAUT PORT DICKSON
JALAN RAJA AMAN SHAH
71000 PORT DICKSON
NEGERI SEMBILAN DARUL KHUSUS



Telefon: 06-6477993
Faks: 06-6477998
Emel : ppdks@marine.gov.my
Laman Web : <http://www.marine.gov.my>

PEKELILING PELABUHAN PORT DICKSON NO. 17/2022
PORT DICKSON PORT CIRCULAR NO. 17/2022

DARIPADA : PENGARAH LAUT WILAYAH TENGAH
FROM : DIRECTOR OF MARINE CENTRAL REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN
PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA
TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS &
AGENTS AND THE GENERAL SHIPPING COMMUNITY

TARIKH / DATED : 23 Jun 2023 / 23 Jun 2023

KERJA-KERJA PENYELAMAN BAGI PENUKARAN HOSE
SINGLE BOUY MOORING (SBM) PETRON

Tempoh:
25 Jun 2023 sehingga 01 Julai 2023

Lokasi:

Single Buoy Mooring (PETRON)	
Latitude	Longitude
02° 31.3' U	101° 47.1' T

DIVING WORKS FOR CHANGING HOSE AT PETRON
PORT DICKSON REFINERY

Duration :
25 Jun 2023 until 01 July 2023

Location:

Single Buoy Mooring (PETRON)	
Latitude	Longitude
02° 31.3' N	101° 47.1' E

Vessel terlibat:

No	Nama	Jenis
1	TAZ 31	Bot Lesen
2	TAZ 3	Bot Lesen
3	OPL MARINE 54	Bot Lesen
4	OPL MARINE 50	Tongkang Kren
5	OPL MARINE 22	Bot Tunda

Vessel involved:

No	Name	Type
1	TAZ 31	Boat License
2	TAZ 3	Boat License
3	OPL MARINE 54	Boat License
4	OPL MARINE 50	Crane Barge
5	OPL MARINE 22	Tug Boat

Perhatian

Semua kapal-kapal dan pelaut-pelaut adalah dinasihatkan untuk menjauhi dan berhati-hati apabila berhampiran dengan kawasan persekitaran tersebut.

Terima kasih.

Caution

All vessels and mariners are advised to keep clear of the area and to navigate with caution when in the vicinity.

Thank you.

(MOHD ABDUL HAKIM BIN CHE MOHD NOR)
b.p Pengarah Laut Wilayah Tengah
Director of Marine, Central Region

